

TECH - TIP

An update on constructing the Force 10 system

Date Raised: Friday, 4 June 2010

By: R Gittins

New Rollformed Joist Profile

The joist rollformer is now in place and operational, below is a photo of the new joist as it comes out of the rollformer, this has had minor modifications in its appearance however is installed and performs the same.

